

EXAMPLE PRICES ONLY. Not a quote and not a market rate.

Clearseason Comfort

8 Coil Rd
Nashville, TN 37203
(615) 555-0166

INVOICE

INV-3901

Issued October 8, 2026

Due October 8, 2026

BILL TO

The Nguyen household

Job site: 12 Willow Court
Outdoor unit example: Northwind NW-36
Serial EX-36001
Filter size 20x25x1

Description	Qty	Rate	Amount
Diagnostic fee	1	\$95.00	\$95.00
Labor, capacitor replacement and refrigerant charge	1.5	\$125.00	\$187.50
Dual run capacitor, new	1	\$48.00	\$48.00
Refrigerant R-410A, per pound, example quantity	2	\$55.00	\$110.00
Filter, 20x25x1	1	\$18.00	\$18.00
Maintenance-plan credit: diagnostic waived for a current member	1	-\$95.00	-\$95.00
Subtotal			\$363.50
Total due			\$363.50

Payment methods: Credit/Debit Card, Check, Cash

Notes

Example prices for a cooling repair. Not a seasonal special.

The diagnostic is listed, then credited, because this household is on a maintenance plan in the sample. If they were not, you would delete the credit line and the diagnostic would stay. If they decline the repair, delete the parts and labor and leave the diagnostic.

Refrigerant is 2 pounds of R-410A in this story. That is not a charge recommendation for any real unit. Write the type and the pounds you actually put in. Refrigerant handling has rules. Check the ones that apply to your shop.

Equipment on the job: Northwind NW-36, serial EX-36001, both made up. Filter size is on the bill so the next visit is faster.

Warranty to edit: 1 year on the repair labor in this sample, manufacturer warranty on the capacitor. Due when the visit ends.

Made as a free sample by PaidPilot (paidpilot.io). Replace the example figures before you send it.